



ALERT SERVICE BULLETIN

INSPECTION OF THE OIL FILTER

PART NO. 825701

FOR ROTAX® ENGINE TYPE 912 AND 914 (SERIES)

ASB-912-045UL R1

ASB-914-030UL R1

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 914 UL from S/N 4,418.793 to S/N 4,418.841
- 912 UL from S/N 4,406.458 to S/N 4,406.522
- 912 ULS from S/N 5,643.838 to S/N 5,643.932
- 912 ULSFR from S/N 4,430.002 to S/N 4,430.031

Also affected, are all engines equipped with oil filter part no. 825701, shipped from ROTAX® as a spare part between July 8th 2004 to October 07th 2004 at maintenance event.

For complete instructions and compliance to this service bulletin refer to Alert Service Bulletin ASB-912-045, Alert Service Bulletin ASB-914-030, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.